


# M18FROS125-0B Akku-Exzenterschleifer XXX

4933498253 - M18FROS125-0B - 4000503910





| Position | Quantity | Description       | Part number | EAN           |
|----------|----------|-------------------|-------------|---------------|
| 0001 1   | 1        | SCHUTZ            | 4931506758  | 4058546560720 |
| 0020 2   | 10       | SCHRAUBE          | 4931465499  | 4058546235994 |
| 0022 3   | 2        | GUMMIKAPPE        | 4931506759  | 4058546560737 |
| 0023 4   | 1        | GEHAEUSEDECKEL    | 4931506760  | 4058546560744 |
| 0024 5   | 2        | SCHRAUBE          | 4931472686  | 4058546329884 |
| 0025 6   | 1        | GEHAEUSEDECKEL    | 4931506761  | 4058546560751 |
| 0026 7   | 1        | ABSAUGVORRICHTUNG | 4931506762  | 4058546560768 |
| 0027 8   | 2        | SCHRAUBE          | 660570005   | 4002395827329 |
| 0028 9   | 6        | SCHRAUBE          | 4931453223  | 4002395152568 |
| 0031 10  | 6        | SCHRAUBE          | 4931506763  | 4058546560775 |
| 0032 11  | 1        | BREMSRING         | 4931506764  | 4058546560782 |
| 0033 12  | 1        | KISSEN            | 4931506765  | 4058546560799 |
| 0034 13  | 4        | SCHRAUBE          | 4931435649  | 4002395862931 |
| 0038 14  | 2        | GUMMIBUECHSE      | 4931506766  | 4058546560805 |
| 0039 15  | 2        | GUMMIKAPPE        | 4931506767  | 4058546560812 |
| 0046 16  | 1        | LEISTUNGSSCHILD   | 4931506768  | 4058546560829 |
| 0060 17  | 1        | ELEKTRONIK        | 4931506769  | 4058546560836 |
| 0061 18  | 1        | ROTOR             | 4931506770  | 4058546560843 |
| 0062 19  | 1        | GEHAEUSE          | 4931506771  | 4058546560850 |
| 0063 20  | 1        | STAUBFUEHRUNG     | 4931506772  | 4058546560867 |
| 0064 21  | 1        | ABSAUGVORRICHTUNG | 4931506773  | 4058546560874 |
| 0065 22  | 1        | ABSAUGSTUTZEN     | 4931494106  | 4058546429874 |
| 0702 23  | 1        | EINSATZ           | 4931506774  | 4058546560881 |